











- | | |
|----------------------------------|------------------------------|
| (D) Montageanleitung | (GB) Assembly instructions |
| (FR) Notice de montage | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montażu |
| (CZ) Montážní návod | (SK) Návod na montáž |
| (HU) Szerelési útmutató | (RO) Instrucțiuni de montaj |
| (TR) Montaj talimatları | |


















60 min






Nº	Size/MaB	Qty	✓
1	1750x450x20	1	
2	1750x450x40	1	
3	369x448x45	1	
4	369x448x45	1	
5	369x400x20	1	
6	369x400x20	1	
7	484x360x20	2	
8	482x363x55	1	
9	482x363x55	1	
10	682x180x20	2	
11	350x130x15	2	
12	350x130x15	2	
13	626x130x15	2	
14	638x347x5	2	
15	381x491x5	2	
16	381x684x5	1	
17	150x100x100	4	
18	140(+10)x60x60	1	
19	212x40x20	1	

A1 x13  Ø7x50	B1 x20 	C1 x12  Ø15	C2 x8  Ø12	J1 x6  3.5x16
J4 x14  4x35	F1 x2  L350 Push to open	R1 x4 	K1 x32  Ø8x35	J2 x36  4x16
Z2 x8 	N1\1 x2  Tip-on	N1\2 x2  Tip-on	N1\3 x2  Tip-on	N1\4 x2  Tip-on
L07 x4 	M07 x4  Push to open	W1 x6 	O1 x1  k4 mm	




1

C1 x6




Ø15

K1 x8




Ø8x35


L07 x4





J2 x8



4x16




K1




J2

L07




C1



K1


2

N1\3 x2




Tip-on

N1\2 x2




Tip-on

N1\1 x2




Tip-on


J2 x4



4x16





1



J2

N1\1

N1\2








N1\3

3

3


B1

B1 x12




4

C1 x6




Ø15

K1 x8



Ø8x35


F1 x2









L350

Push to open


J2 x8




4x16



5





6



7


A1 x12

O1 x1



A1

2



8


L1

$L1=L2$ 😊✓

L2




9

J1 x6




3.5x16

W1 x6




10 x2


K1 x4




Ø8x35



11




K1 x4



Ø8x35

A1 x1




Ø7x50

O1 x1





k4 mm



12

J4


J2



R1 x4




J4 x6




4x35




J2 x8




4x16







13

N1\4 x2  Tip-on	M07 x4  Push to open	J2 x8  4x16
---	---	--




14 x2


B1 x8 	C2 x8  Ø12	K1 x8  Ø8x35
---	---	---




15 x2




J4 x8









4x35





16 x2



17 x2





18 x2



19 x2

Z2 x8



20 x2

