





(D) Montageanleitung

(FR) Notice de montage

(NL) Handleiding voor de montage

(CZ) Montážní návod

(HU) Szerelési útmutató

(TR) Montaj talimatları


(GB) Assembly instructions

(IT) Istruzioni di montaggio



(PL) Instrukcja montażu

(SK) Návod na montáž

(RO) Instrucțiuni de montaj




















60 min



No	Size/MaB	Qty	✓
1	1550x450x20	1	
2	1550x450x40	1	
3	620x448x45	1	
4	620x448x45	1	
5	620x400x20	1	
6	620x400x20	1	
7	484x360x20	2	
8	482x614x55	1	
9	482x614x55	1	
10	482x180x20	2	
11	350x130x15	2	


No	Size/MaB	Qty	✓
12	350x130x15	2	
13	426x130x15	2	
14	438x347x5	3	
15	482x248x20	1	
16	350x160x15	1	
17	350x160x15	1	
18	426x160x15	1	
19	632x491x5	2	
20	632x484x5	1	
21	150x100x100	4	
22	212x40x20	1	

A1 x12  Ø7x50	B1 x24 	C1 x12  Ø15	C2 x12  Ø12	K1 x40  Ø8x35	J1 x8  3.5x16	J2 x42  4x16
J4 x18  4x35	F1 x3  L350 Push to open	R1 x4 	N1\4 x2  Tip-on	N1\3 x2  Tip-on	N1\2 x2  Tip-on	N1\1 x2  Tip-on
Z2 x8 	W1 x8 	O1 x1  k4 mm	P1 x1 	G1 x1 	V1 x1 	




1

C1 x6




Ø15

K1 x8




Ø8x35


L07 x4





J2 x8



4x16





K1




J2

L07




2

N1\3 x2




Tip-on

N1\2 x2




Tip-on

N1\1 x2




Tip-on


J2 x4



4x16




1




J2

N1\1



N1\2







N1\3

3


B1

B1 x12




4

C1 x3




Ø15

K1 x4




Ø8x35

F1 x3






L350
Push to open

J2 x6




4x16




5

C1 x3




Ø15

K1 x4




Ø8x35

F1 x3




L350
Push to open

J2 x6




4x16




6



12x




7





8





9




10




11 x2




12



K1 x4



Ø8x35



13


J4

J2

R1 x4




J4 x6





4x35


J2 x8



4x16




R1




14

N1/4 x2




Tip-on

M07 x4







Push to open

J2 x8




4x16




15 x2

B1 x8




C2 x8









Ø12


K1 x8




Ø8x35




16 x2




J4 x8



4x35



17 x2




18


B1

15

B1 x4




C2 x4



Ø12

K1 x8



Ø8x35

C2

16

K1

17

18


19

16

18

17

J4 x4




4x35

J4

20







4x





15




14












21 x2






22 x2



J2 x2	P1 x1	G1 x1	V1 x1
			
4x16			

A**A****B****C****D****E****F****F**



25

Z2 x8

